

**SECRET****PRIORITY****1**25X**SECRET** 191937Z CITE [ ] 17901967 SEP 19 20 11Z  
OUT6313325X**PRIORITY** [ ]

IDEALIST

SUBJ: EVALUATION OF MISSION C277C

25XATTN: [ ]

1. CAMERA B-228 WAS USED ON MISSION C277C FLOWN ON 26 AUGUST 1967. PROCESSING WAS ACCOMPLISHED IN THE FIELD.

2. ORIGINAL NEGATIVE:

A. RESOLUTION IS GOOD. DENSITY IS GOOD.

B. 9R SIDE: EDGE STATIC IS PRESENT ALONG THE OUTBOARD EDGE THROUGHOUT THE MISSION. ROLLER CHATTER IS PRESENT ON THE INBOARD EDGE OF THE FIRST FEW FRAMES. HEAT SPLICES APPEAR BETWEEN FRAMES 161/162, 428/429, 835/836, 1243/1244, 1642/1643, 2049/2050, AND 2447/2448. A MANUFACTURER'S SPLICE IS PRESENT IN FRAME 1637.

C. 9L SIDE: EDGE STATIC IS PRESENT ON INBOARD EDGE FOR THE FIRST 500 FRAMES. EMULSION LIFTS AND ASSOCIATED PLUS DENSITY STREAKS APPEAR ON FRAMES 275 AND 276. HEAT SPLICES OCCUR IN OR BETWEEN FRAMES 168/169, 430/431, 925, 1341/1342, 1743/1744, 2144, AND 2547. MANUFACTURER'S SPLICES OCCUR IN FRAMES 298 AND 1928.

D. BOTH SIDES: THERE IS A CAMERA OFF/ON BETWEEN FRAMES 14 AND 15. MODE ONE OF CAMERA OPERATION WAS USED THROUGHOUT. CYCLE RATE IS 4.0 SECONDS AND OVERLAP IS APPROXIMATELY 60 PERCENT BETWEEN VERTICAL FRAMES. THE LAST TITLED FRAME IS 2809.

3. POSITIVE:

A. PI SUITABILITY IS GOOD.

B. PRINTING AND PROCESSING ARE GOOD.

C. CLOUDS OBSCURE APPROXIMATELY 20 PERCENT OF THE MISSION.

**SECRET**

END OF MESSAGE

NGA review(s) completed.

2

1

245

25X1

**1****SECRET**

GROUP 1  
Excluded from automatic  
downgrading and  
declassification